


Hillsboro Transit Center Progress Report

September 2021



PROGRESS



Work completed to date:

- Foundations for canopy structures and waiting facility
- Canopy steel installation
- Waiting room steel installation
- Waiting facility masonry

Upcoming work:

- Site preparation including bus lane and sidewalk
- Brickwork on waiting facility
- Painting of canopy steel



On-street canopies for bus boarding (looking south)



Climate-controlled waiting facility (looking north)



On-street canopies for bus boarding (looking north)